




RunFile_004.drf - BASELINE - Run Conditions: 73.93 °F, 29.05 in-Hg, SAE: 1.02

RunFile_007.drf - SP1837 - Run Conditions: 78.43 °F, 29.08 in-Hg, SAE: 1.02

DYNOJET RESEARCH

CF: SAE Smoothing: 2

INJEN TECHNOLOGY



MR - TECHNOLOGY

RunFile_004.drf - BASELINE - Run Conditions: 73.93 °F, 29.05 in-Hg, SAE: 1.02

Run Type: RO Date: 4/14/2009 11:49:00 AM

2009 Mitsubishi Lancer Ralliart 2.0L Turbo

RunFile_007.drf - SP1837 - Run Conditions: 78.43 °F, 29.08 in-Hg, SAE: 1.02

Run Type: RO Date: 4/14/2009 12:24:45 PM

2009 Mitsubishi Lancer Ralliart 2.0L Turbo